








## 15 year exposure test result in C5 corrosive environment

We conducted an exposure test on Miyakojima Island, where the corrosivity category is the C5 environment. Rust occurred on the entire surface of general paint in 3 years, but ROVAL did not show rust even after 15 years.



**This is the data that proves compliance with ISO12944 C5-High.**

ROVAL Cold Galvanizing Compound			
			
Before exposure	3 years	10 years	15 years
		 <p>Miyakojima exposure test center</p>	
Anticorrosive paint + Phtalic topcoat			

